

Product / Process Change Notice

Parts Affected:

CEN1180 surface mount, Silicon Controlled Rectifier in the SOT-23 case.

Extent of Change:

Alternate marking code is being added to product and product data sheet.

Reason for Change:

To allow for an alternate marking code.

Effect of Change:

CEN1180 devices are being manufactured with marking code of **P2B** or **P2A**.

Effective Date of Change:

December 20, 2010